


I = 0 A

Poles = 4



— Voltage [V]    — Power [kW]    — Torque [Nm]