


I = 4 A

Poles = 2



— Voltage [V]    — Power [kW]    — Torque [Nm]