


I = 6 A

Poles = 2



— Voltage [V] — Power [kW] — Torque [Nm]